

# KEY POINTS

The placement of the cup can be problematic, either due to a trapezium of small diameter or secondarily after the failure of a previous prosthesis.

